



Calibration will be done in next step!




Step 3
calibrate stage

3.1 . Type 50 for both speed


3.2 Click **Calibrate**
Stage will move in x-y
direction

3.3 Click **Calibrate**
Stage will move in z
direction


Step 4: Import new experiment templates



4.4 File location




4.5 Select the new experiment template



Always leave it on for 37C heating



Oil for 63x objective is inside the imaging chamber at 37C



Do not press "Reset"